



VNA measured insertion loss of the exiting boards + SMA Jumper.

Pair	Serial Cables Trace + SMA Jumper
TX1	-2.21
TX3	-2.74
RX1	-4.43
RX3	-4.34